

**PRESSURE MEASUREMENT**

<b><u>Range</u></b>	<b><u>Accuracy</u></b>	<b><u>Cal. Device</u></b>	<b><u>Notes</u></b>
1 to 600 barg 10 to 8000 psig	0.03%	Budenberg "D" DWT	Calibrations on Tellus oil. Water and other fluids on request.
1 to 1200 barg 10 to 16000 psig	0.05%	Budenberg "H" DWT	Calibrations on Tellus oil. Water and other fluids on request.
10 to 40000 psig	0.04%	Budenberg 580 EHx	Calibrations on Tellus oil.
1 to 1200 bar/ 16000 psi	0.25%	Budenberg Comparator	Calibrations on Tellus oil. Used where DWT is unsuitable.
-1 to +20 barg	±0.005% of fs +0.005% Rdg	Druck Pace 1001	Pneumatic pressure indicator
1000 barg	±0.025% of FS	Druck PC6	Digital gauge
1000 barg	±0.05% of fs	Druck DPI104/IS	Digital gauge
20 barg	±0.05% of fs	Druck DPI104/IS	Digital gauge
-1 to +20 barg	±0.025% of FS + 1lsd	Druck DPI610/IS	Pneumatic calibrator
2 barg	±0.05% of FS + 1lsd	Druck DPI601/IS	Pneumatic calibrator

Last revision date: 18<sup>th</sup> August 2023

Last review date: 18<sup>th</sup> August 2023